

Date	Complaint received from	Nature of complaint	Outcome of investigation
08/1/23	Public (EPA)	Email received from the EPA on 24/01/23 regarding concern around sediment laden water entering Bungonia Creek with a drop pin and photo provided.	Bungonia creek monitoring: TSS results show no impact on the creek from the main gully system. Latest TSS results obtained on 10/11/22 were 29mg/L and 25mg/L for Bungonia Creek up and Bungonia Creek down respectively. 24/1/23: Drone flight attempted- very difficult to locate the position of the blowhole and maintain drone signal from within the mine. No intrusion of water was visible. 30/1/23: Service conducted and data download on the Main Gully Overflow monitor and weather station for rain data. There have been no overflow events for the months of Dec 2022 and January 2023. It was determined that the sediment laden water observed was not contributed to by the mines Main Gully water surface water catchment but rather the underground 'blowhole' cave (also known as B68 Main Gully Spring) system which is fed by the greater area.
24/2/23	Public (NPWS)	Email received from National Parks and Wildlife regarding the sighting of a metal pipe in Bungonia Creek by a member of the public on 19/2/23.	Bungonia Creek was inspected by a Boral Environmental Representative on 17/2/23 and 22/2/23 with no sighting of the metal pipe. 24/2/23: National Parks agreed that it would currently be highly unlikely for such material to escape over the edge of the Mine's South Pit and that such material could have washed down the creek from an upstream location during a rain event. National parks was happy that the creek had been inspected and Boral has requested photos in the event that such an observation arises again to assist with determining the source.
15/6/23	Public (Council)	Email received from the council on 15/5/23 notifying the site that there had been a Pampas Grass sighting and providing a map.	16/6/23: The site confirmed that it is in compliance with the site's Weed Management Plan which is displayed on the Boral website. Under this management plan, Pampas is sprayed during the December to May period and again during the September to November period. Council suggested that Boral remove the heads from any remaining accessible Pampas plants.

Date	Complaint received from	Nature of complaint	Outcome of investigation
			The Weed Management Plan was sent to Council in a follow up email and a contractor was engaged to remove any remaining heads from accessible Pampas grass, with the next spray for Pampas grass scheduled for the September to November period via foot and drone for any inaccessible plants.
14/3/25	Public	Community Member contacted Boral notifying the site that they can hear a fan like noise coming from the mine.	14/3/25 Boral received a call from a community member with a noise complaint. Peppertree Site and Production Managers went to the location and could hear rocks falling onto the surge however the noise in the complaint was described as a fan. The kiln, top, bottom section of production and reclaimer were not working at the time of complaint as such the noise has not been identified. The noise complaint was made for between 5am – 7:45am. The weather conditions were categorised as strong to severe inversion conditions for this time.
6/5/2025	Public	Community member contacted the EPA with a complaint about the water quality at Bungonia Creek.	On 6/5/25 Boral received an email from the EPA stating that they had been contacted by a member of the public with a complaint regarding the water quality at Bungonia Creek. Photos were submitted from Sunday the 4 th May showing silty water. Main Gully had been checked three days prior to this, with images from the inspection showing good water quality (not silty) and no overflow event. There was no rain between Main Gully inspection and the day the member of the public was there and took photos. 22/5/25 the EPA were sent water testing results that showed no difference to previous results.
14/07/2026	Employee	Employee reported that while driving to work on Marulan South Road, an oncoming truck flicked up two rocks, damaging his windscreen.	Boral replaced the broken windscreen.

Date	Complaint received from	Nature of complaint	Outcome of investigation
16/07/2026	Public	A complaint was received from a Marulan South Road resident regarding truck braking noise at approximately 1:35 am. Investigation indicated that trucks were slowing down near the second speed check sign towards the mine, resulting in braking activity close to nearby residences. A request was made to relocate the sign further west to reduce noise impacts.	The speed check sign was identified as council owned and the matter referred to Council.
23/07/2026	Public	A local resident raised concerns regarding the behavior of some trucks associated with increased truck movements, alleging incidents of speeding and tailgating.	Truck drivers were reminded again of the speed limits and general acceptable driving behaviours.