

Community Consultative Committee

Peppertree Quarry & Marulan South Limestone December 2023



AGENDA

- 1. Welcome and introductions
- 2. Confirmation of minutes and actions
- 3. Business arising
- 4. Correspondence
- 5. Operations over the last 3 months
- 6. Environmental performance
 - a. Incidents
 - **b.** Complaints
 - c. Air
 - d. Noise
 - e. Blast
 - f. Water surface and ground
 - g. Heritage
 - h. Ecology
 - 7. Stakeholder Engagement
- 7. Stakeholder Engagement 8. Plans for the next 3 months
- 9. General Business
- 10. Next meetings March 2023







01 Welcome and apologies



Confirmation of minutes





J72

STARTER ISOLATOR

BATTERY ISOLATOR

JUMP START R CEPTACLE 24 VOLT Business arising



Correspondence Sept 2023 – Nov 2023



Peppertree Quarry

Department of Planning and Environment

Update of Environmental Management Plans

Resources Regulator

Regulator Targeted education program - Roads and other vehicle operating areas

Goulburn Mulwaree Council

Nil

Geoff Clark

Weather data reviews – weather station monthly reviews





Marulan South Limestone

EPA

Nil

Resources Regulator

- Rehabilitation Management Plan being finalised Forward Program submitted
- Planned Structural Integrity Inspection as part of RR targeted intervention program

Department of Planning and Environment

- Endorsement of Independent Auditor
- Update to Environmental Management Plans

Goulburn Mulwaree Council

- Work ongoing on designs of upgrade for Marulan South Road. Road upgrade scheduled for Mid 2025
- Section 7.11 contributions

Geoff Clark

Weather data reviews – weather station



Operations Past 3 months





S- CONTRACT

Peppertree Quarry

Safety

No LTI/MTI over the last three months. Hazard reporting has improved. Safety training on Mental health and Emergency Response for Bush fire Preparedness training. Peppertree celebrated one year of zero MTI. One minor injury due to slip and fall.

Overburden

Overburden is being stripped focusing in a Southerly direction circa 1.5 million m3 has been moved. Peppertree moved into the next stage of stripping in September 2023 were it will be a further 1.2 million m3 in this phase.


Pit Update

Contract crushing on the RL525, in pit crushing will continue in a southerly direction directly following stripping.

Processing (STQ)

Production on target.

People



Marulan South Limestone

Safety

No LTI since last meeting and 0.00 TRIFR. Mental health first aid training and Men's mental health 'Are You Bogged' Presentation.

Ongoing commitment to maintain currency of employee skills including various trades and high-risk activities such as confined space, working at heights. Hazardous materials risk assessment and local RFS site visit.

Overburden


Overburden stripping has been progressing at a steady 375,000t/month.

Limestone Extraction

Extracting at a rate of 250,000t/month.

People

Total of 98 employees on site. New production operator, Mechanical Fitter promoted to Maintenance Superintendent. Two 10- year anniversaries celebrated. Some staff m





Environmental Performance



06.1


Environmental Performance Peppertree Quarry






Environmental Incidents Jan 2017 to August 2023






Nil Incidents (September to November)

Environmental Complaints Jan 2017 to August 2023



> Noise -1 (Oct)

Air – Dust deposition Gauge D1




Annual Average goal of 4gm2/month

In compliance Annual average below goal at the boundary



Air – Dust Deposition Gauge D2




:{•];7

Annual Average goal of 4gm2/month

In compliance

Air – Dust Deposition gauge D3




Annual Average goal of 4gm2/month

In compliance

Air – PM10 annual average






Annual Average goal of 25ug/m3

In compliance


Air – PM10 24 Hour performance



24 hour goal of 50ug/m3

In compliance

Air – Total Suspended Particulates




Annual Average goal of 90ug/m3

In compliance

Air - PM2.5





In compliance for the past 3 months. *exceedance in October due to westerly wind and wind speed conditions but extrapolated data to the nearest boundary was below the threshold.

Noise – quarterly monitoring




Monitoring was undertaken over 27th and 28th September 2023

Results for the September round are in compliance.

Next round due in October-December.


Monitoring to be conducted on the 11th to the 13th of December.

Blasting - Overpressure



In Compliance

Blasting – ground Vibration



!:{●];**?**

In Compliance

Surface Water




Quarterly monitoring round undertaken in July – September 2023 with sampling on Friday 8th September 2023

No issues with water supply or quality over the last 3 months

Next round of sampling to be conducted October – December with sampling done on Wednesday 5th December 2023 still awaiting results.


Surface water - pH






Within guideline for Sept samples

Surface water - Turbidity



Below guideline for Sept samples


Surface water – Total dissolved solids



:{•];7

Below guideline for Sept samples with exception of Marulan South Creek & main dam.


Surface water – total Phosphorus



Below guideline for Sept samples



Surface water - Total Nitrogen



:{•}RA

Below guideline for Sept samples

Environmental Flow

BORAL	®


year	total in	10%	total out	in	comment
Apr-22	30.3	3.03	656.16	ves	Rainfall -
May-22	22.6	2.26	316.52	yes	Rainfall -
Jun-22	3.1	0.31	6.6	yes	
Jul-22	60.6	6.06	820.91	ves	Rainfall -
Aug-22	34.2	3.42	341.8	ves	Rainfall -
Sep-22	18	1.8	22.88	ves	
Oct-22	62.5	6.25	999.7	ves	Rainfall -
Nov-22	42.2	4.22	411.49	ves	Rainfall -
Dec-22	0.9	0.09	1.34	ves	
Jan-23	15	1.5	15.48	ves	
Feb-23	1.1	0.11	7.02	ves	
Mar-23	2.5	0.25	3.67	ves	
Apr-23	16	1.6	3.76	ves	
May-23	15	1.5	15.74	ves	
Jun-23	nil	nil	3.46	yes	
Jul-23	1.8	0.18	3.79	yes	
Aug-23	nil	nil	3.69	yes	
Sep-23	nil	nil	3.4	yes	
Oct-23	nil	nil	3.44	yes	
Nov-23					

Ground water

- > Monitoring conducted in September.
- > Results all good, next round in the coming month.
- > Results show no changes to the groundwater



Ground water – water levels







Artefact analysis is continuing

Temporary Scar tree relocation done in November and display still being planned, currently undercover near the P2 dam area.







Ecology



Three-year plan developed for ongoing rehabilitation and maintenance

- 4Ha Hydromulching of SOE completed in September.
- Continuous monitoring of rehab trees and direct seed planting on site.

Weed management undertaken in the last couple of months. Focus on black berry & Tussock.

Rapid Visual Assessment and Nest Box Inspection completed in November.

Few feral goats have been spotted onsite

NPWS conducted aerial shooting in Sept and a total of 50 goats removed. Ongoing pest monitoring. Next round of shooting scheduled for the 11th to 15th Dec.



06.2


Environmental Performance Marulan South Limestone






Environmental Complaints Jan 2017 to Nov 2023





No Environmental Complaints last quarter


Air – Dust deposition Site 1



:{●];**7**

Annual Average goal of 4gm2/month In compliance


Air – Dust deposition Site 2



:{•]:**7**-

Annual Average goal of 4gm2/month In compliance

Air – Dust deposition Site 3




:{•];**7**.

Annual Average goal of 4gm2/month

In compliance Annual average below goal at the boundary

Air – PM10 annual average






Annual Average goal of 25ug/m3

In compliance


Air – PM10 24 Hour performance



24 hour goal of 50ug/m3

In compliance

Air – Total Suspended Particulates




Annual Average goal of 90ug/m3

In compliance

Air - PM2.5





In compliance for the past 3 months. *exceedance in October due to westerly wind conditions but extrapolated data to the nearest boundary was below the threshold.

Noise – quarterly monitoring




Monitoring was undertaken on 27th and 28th September 2023 with results in compliance

Next round due in December.


Blasting - Ground Vibration





In Compliance

Blasting – Overpressure



In Compliance



Surface Water




Quarterly monitoring round undertaken 21st-22nd August 2023


No issues with water supply or quality over the last 3 months

Surface water - pH






Surface water – Total Suspended Solids




KORA

Surface water – Nitrogen




:{•];**7**

Surface water – Phosphorus




·:{•];7










Within Guideline Limits: No oil and Grease detected















Ecology

- 4Ha hydromulching and 1300 trees deferred to Autumn due to forecasted hot, dry summer.
- Weed Control: Control undertaken on Tussock, Pampas and Thistle
- Pest Control: Aerial Cull in conjunction with NPWS



Heritage



- BORAL®
- Historic Heritage works completed across the site with excavation and archiving of the old kiln group
- Second round of Aboriginal Artefact collection to commence March 2024

07

Stakeholder Engagement






- 900 copies of the Marulan Newsletter printed on a monthly basis for the Marulan Community
- Goulburn Community Bike Day Sponsored
- Tallong Public School Presentation Day- Sponsored the Boral Numeracy Award.
- Purchased Ngunnawal Plant Use Books from the Bungonia Focus Group after attending Bungonia Bush Tucker Garden Tour





80

Operations Next 3 months





Peppertree Quarry

Safety

Focus on the "life saving commitments"- particular focus for the year is "Injury free in 2023" focus on Hot weather and hazard reporting which will help to reduce incidents.

Overburden

Continue to strip in a Southerly direction.

Pit Update

Metso has been realigned to follow overburden stripping in a Southerly direction

Processing (STQ) Continue to supply aggregates and sand to Sydney metro.

Transport

Commence product despatches by truck from shared road sales stockpile area as per Marulan South Limestone development consent.

People

New Maintenance Admin Role

Safety

Focus on VOC renewal and new apprentice training. Implementation of new Employee Assistance Program (EAP), Sonder.

Overburden


Work ongoing to replace some of the ageing process infrastructure. Overburden from the North-East and West of pit continues to be placed in the South and Western overburden emplacements.

Pit Update

Limestone extraction will continue in the North and Central areas of the pit. Finalising the RMP in order to move to new emplacement areas as defined in the EIS.

People

As part of commitment to the local community, three apprentices from the local catchment area will be engaged in 2024; mechanical fitter, electrical and welder/fabrication along with the recruitment of a new Maintenance Manager and Technical Manager.





09

General Business







Other :

Next meeting

March 2024



Building something great



Thanks for your participation