

Environmental Monitoring Report

Real-time Air Quality monitoring

Dunmore Quarry


September 2026 Report

Reporting period: August 2025 to August 2026. Realtime air quality monitoring is conducted as per condition M2.2 of EPL 77.


Dunmore Quarry Information

Premise Details	Boral – Dunmore Quarry
Address	Princes Highway, Dunmore NSW, 2529
Licensee	Boral Resources (NSW) PTY LTD
EPL No	77
EPL Location	EPA website - Licence 77


DT1 August 2026 hourly rolling averages




DT2 August 2026 hourly rolling averages



DT3 August 2026 hourly rolling averages



DT4 August 2026 hourly rolling averages



DMP	Month	Daily averages			Daily limit	Annual limit			Comments
		PM2.5 µg/m3	PM10 µg/m3	TSP µg/m3		PM10 µg/m3	PM2.5 µg/m3	TSP µg/m3	
DMP1	Aug-26	2.44	3.60	4.04	50	25	8	90	
DMP2	Aug-26	2.67	3.63	3.92	50	25	8	90	Unit broken - off between 27-31 August
DMP3	Aug-26	5.16	6.85	7.41	50	25	8	90	
DMP4	Aug-26	1.99	3.81	4.96	50	25	8	90	
DMP1	Jul-26	1.74	2.78	3.21	50	25	8	90	
DMP2	Jul-26	2.09	2.90	3.17	50	25	8	90	
DMP3	Jul-26	3.92	5.33	5.83	50	25	8	90	
DMP4	Jul-26	1.73	3.75	5.03	50	25	8	90	
DMP1	Jun-26	1.75	2.93	3.41	50	25	8	90	
DMP2	Jun-26	2.1	3.17	3.51	50	25	8	90	
DMP3	Jun-26	4.21	6.42	7.2	50	25	8	90	
DMP4	Jun-26	1.63	3.6	4.93	50	25	8	90	
DMP1	May-26	2.95	4.57	5.17	50	25	8	90	
DMP2	May-26	3.50	5.23	5.74	50	25	8	90	
DMP3	May-26	6.05	8.64	9.42	50	25	8	90	
DMP4	May-26	2.52	5.49	7.19	50	25	8	90	
DMP1	Apr-26	3.08	4.76	5.41	50	25	8	90	
DMP2	Apr-26	3.85	5.89	6.49	50	25	8	90	

DMP3	Apr-26	6.78	9.35	10.11	50	25	8	90	
DMP4	Apr-26	2.76	5.87	7.63	50	25	8	90	
DMP1	Mar-26	4.31	8.02	9.27	50	25	8	90	
DMP2	Mar-26	5.89	11.09	12.70	50	25	8	90	Solar system failure led to missing data between 22-24 and 27-30 March
DMP3	Mar-26	9.30	16.85	19.25	50	25	8	90	
DMP4	Mar-26	3.77	10.26	13.68	50	25	8	90	
DMP1	Feb-26	6.31	10.27	11.57	50	25	8	90	
DMP2	Feb-26	7.53	12.24	13.61	50	25	8	90	
DMP3	Feb-26	11.73	18.19	20.29	50	25	8	90	
DMP4	Feb-26	5.60	12.10	15.45	50	25	8	90	
DMP1	Jan-26	6.57	18.88	20.04	50	25	8	90	
DMP2	Jan-26	2.75	4.12	4.31	50	25	8	90	
DMP3	Jan-26	10.22	34.34	36.63	50	25	8	90	
DMP4	Jan-26	1.66	3.86	4.10	50	25	8	90	
DMP1	Dec-25	7.74	22.95	24.38	50	25	8	90	
DMP2	Dec-25	1.49	2.82	2.95	50	25	8	90	
DMP3	Dec-25	6.57	17.91	18.30	50	25	8	90	
DMP4	Dec-25	1.83	105.12	14.32	50	25	8	90	Issues with data synchronization led to very high values being recorded
DMP1	Nov-25	4.85	17.31	19.11	50	25	8	90	
DMP2	Nov-25	1.59	2.85	2.95	50	25	8	90	
DMP3	Nov-25	7.50	28.63	31.31	50	25	8	90	
DMP4	Nov-25	1.07	3.85	4.07	50	25	8	90	
DMP1	Oct-25	5.32	16.93	18.58	50	25	8	90	
DMP2	Oct-25	1.37	2.45	2.59	50	25	8	90	
DMP3	Oct-25	7.62	24.72	26.80	50	25	8	90	
DMP4	Oct-25	1.53	5.05	5.28	50	25	8	90	
DMP1	Oct-25	5.32	16.93	18.58	50	25	8	90	
DMP2	Oct-25	1.37	2.45	2.59	50	25	8	90	
DMP3	Oct-25	7.62	24.72	26.80	50	25	8	90	
DMP4	Oct-25	1.53	5.05	5.28	50	25	8	90	
DMP1	Sep-25	3.23	11.50	12.79	50	25	8	90	
DMP2	Sep-25	0.13	0.20	0.20	50	25	8	90	
DMP3	Sep-25	6.33	19.71	21.57	50	25	8	90	
DMP4	Sep-25	0.51	2.43	2.61	50	25	8	90	
DMP1	Aug-25	2.17	6.79	7.28	50	25	8	90	
DMP2	Aug-25	0.00	0.01	0.01	50	25	8	90	Air pump broken
DMP3	Aug-25	3.99	12.01	12.82	50	25	8	90	
DMP4	Aug-25	0.30	1.32	1.39	50	25	8	90	

Dunmore Quarry Monitoring Locations.



