



Building  
something  
great

# Seaham Quarry

## Environmental Monitoring Report

Surface Water Monitoring Data

April 2026



**Building  
something  
great**

This monitoring report is to satisfy the requirements of Section 66 (6) of the Protection of the Environment and Operations Act 1997, to make available, within 14 days of obtaining any monitoring data that relates to pollution under an Environment Protection Licence

The monitoring of pollutants provided in this report is undertaken as per the requirements of Environment Protection Licence 3956 (EPL: 3956 – Boral Seaham Quarry)

<b>Seaham Quarry Information</b>	
Premise Details	Boral – Seaham Quarry
Address	Italia Road, Seaham NSW 2324
Licensee	Boral Resources (NSW) Pty Ltd
EPL No	3956
EPL Location	<a href="#">ViewPOEOLicence.aspx (nsw.gov.au)</a>
Date of dataset update	16/04/2026

Monitoring data in this report relates to the monitoring undertaken in the reporting period for the following environmental pollutants:

- Surface Water



**Building something great**

## Surface Water Monitoring

Water quality monitoring is conducted as per condition M2 of EPL 3956.

### Qualifications related to Surface Water

Extracted from EPL: 3956

EPA Identification No.	Type of Monitoring Point	Location Description
1	Discharge to Waters Discharge Quality Monitoring	Discharge from Dam A2
2	Discharge to Waters Discharge Quality Monitoring	Discharge from Sediment Basin B4
3	Discharge to Waters Discharge Quality Monitoring	Discharge from Sediment Basin C2
4	Discharge to Waters Discharge Quality Monitoring	Discharge from Sediment Basin E1
5	Discharge to Waters Discharge Quality Monitoring	Discharge from Sediment Basin E2

Water Concentration Limits:

Points 1,2,3,4,5

Pollutant	Units of Measure	50 Percentile concentration limit	90 Percentile concentration limit	3DGM concentration limit	100 percentile concentration limit
Oil and Grease	milligrams per litre				10 &/or none visible
pH	pH				6.5-8.5
Total suspended solids	milligrams per litre				30

Note: Points 2, 3, 4 and 5 were included in the concentration limits table in a variation to the licence in September 2023.



**Building  
something  
great**

Water monitoring requirements:

**POINT 1,2,3,4,5**

<b>Pollutant</b>	<b>Units of measure</b>	<b>Frequency</b>	<b>Sampling Method</b>
Nitrogen (ammonia)	milligrams per litre	Daily during any discharge	Grab sample
Nitrogen (nitrate)	milligrams per litre	Daily during any discharge	Grab sample
Nitrogen (nitrite)	milligrams per litre	Daily during any discharge	Grab sample
Nitrogen (total)	milligrams per litre	Daily during any discharge	Grab sample
Oil and Grease	Visible	Daily during any discharge	Visual Inspection
pH	pH	Daily during any discharge	Probe
TKN-N	milligrams per litre	Daily during any discharge	Grab sample
Total suspended solids	milligrams per litre	Daily during any discharge	Grab sample

Note, Nitrogen was added to the water monitoring requirements in a variation to the licence in April 2024.

Where no results are displayed, no discharges from the monitoring point occurred.

**TABLE 1: Seaham Quarry – Surface Water Monitoring Results**

Monitoring data in **Tables 1 to 5** display the surface water quality data from 19 April 2024 to current with the increased monitoring requirements included in EPL 3956. Data prior to 19 April 2024 is provided in **Table 6**.

**Table 1: EPL ID Point 1 – Discharge from Dam A2**

Date	EPL ID 1 – A2 Dam								Comments
	pH	TSS (mg/L)	O&G	Ammonia as N (mg/L)	Nitrate as N (mg/L)	Nitrite as N (mg/L)	TKN – N (mg/L)	Nitrogen (Total) (mg/L)	
13/08/2025	7.7	24	NV	0.03	1.5	<0.005	<0.1	1.5	The site received 198.2 mm of rainfall between 30 July and 11 August 2025
12/08/2025	7.6	37	NV	0.03	1.6	<0.005	<0.1	1.6	
11/08/2025	7.6	38	NV	<0.02	1.6	0.009	<0.1	1.6	
8/08/2025	7.6	35	NV	0.03	1.3	<0.005	0.3	1.7	
7/08/2025	7.6	32	NV	0.03	1.3	<0.005	0.4	1.7	
6/08/2025	7.5	31	NV	0.02	1.4	<0.005	0.2	1.6	
5/08/2025	7.9	46	NV	0.02	2.1	<0.005	0.1	2.3	
4/08/2025	7.8	48	NV	0.02	2.2	<0.005	<0.1	2.3	
3/08/2025	7.6	48	NV	0.02	2.2	<0.005	<0.1	2.2	
4/07/2025	7.8	41	NV	0.02	3.7	<0.005	<0.1	3.7	
3/07/2025	7.7	53	NV	<0.02	3.4	<0.005	<0.1	3.4	
2/07/2025	7.5	61	NV	<0.02	3.4	0.005	0.2	3.6	
30/05/2025	7.5	56	NV	0.07	3.5	<0.005	0.4	3.9	The site received 497 mm of rainfall between the period 8 May and 23 May 2025
29/05/2025	7.4	69	NV	0.02	3.6	0.02	0.3	3.9	
28/05/2025	7.8	81	NV	0.02	3.4	0.03	<0.1	3.5	
27/05/2025	7.6	86	NV	<0.02	3.5	0.03	0.2	3.6	
26/05/2025	7.6	48	NV	0.02	2.9	0.006	<0.1	3	
24/05/2025	7.7	77	NV	0.02	2.9	0.05	<0.1	3	
23/05/2025	7.4	54	NV	<0.02	2.7	0.01	<0.1	2.8	
21/05/2025	6.9	56	NV	<0.02	1.8	<0.005	<0.1	1.9	



**Building something great**

Date	EPL ID 1 – A2 Dam								Comments
	pH	TSS (mg/L)	O&G	Ammonia as N (mg/L)	Nitrate as N (mg/L)	Nitrite as N (mg/L)	TKN – N (mg/L)	Nitrogen (Total) (mg/L)	
20/05/2025	No sample was able to be collected due to flood waters								
19/05/2025	No sample was able to be collected due to flood waters								
17/05/2025	7.2	23	NV	0.02	3.2	<0.005	0.2	3.4	Greater than 170 mm of rainfall was recorded between 27 April and 2 May 2025
16/05/2025	7.3	59	NV	<0.02	3.2	<0.005	0.3	3.5	
2/05/2025	7.5	35	NV	<0.02	3.2	<0.005	<0.1	3.2	
1/05/2025	7.5	24	NV	0.02	3	<0.005	0.2	3.1	
30/04/2025	7.5	17	NV	<0.02	3	<0.005	<0.1	3	
29/04/2025	7.6	23	NV	<0.02	2.7	<0.005	1.6	4.3	
28/04/2025	7.4	69	NV	<0.02	3.1	<0.005	1.6	4.8	
29/01/2025	7.6	6	NV	<0.02	3.9	0.023	1.3	5.3	
28/01/2025	7.7	7	NV	0.02	3.8	<0.005	1.3	5.2	
27/01/2025	7.7	10	NV	0.06	3.8	0.013	1.3	5.1	
26/01/2025	7.7	13	NV	0.07	3.8	0.014	1.3	5.1	
25/01/2025	7.6	9	NV	0.03	3.9	0.009	1.2	5.1	
24/01/2025	7.5	31	NV	<0.02	4.4	<0.005	0.3	4.7	
23/01/2025	7.3	30	NV	0.02	4.1	<0.005	0.9	5	
22/01/2025	7.3	37	NV	<0.02	3.3	<0.005	0.9	4.2	
21/01/2025	7.3	41	NV	0.02	2.7	0.012	1	3.7	
20/01/2025	7.5	54	NV	<0.02	2.5	<0.005	0.8	3.4	
19/01/2025	7.4	48	NV	0.02	2.5	0.007	1	3.5	
18/01/2025	7.4	66	NV	0.02	2.5	0.006	0.4	2.9	
17/01/2025	7.5	60	NV	<0.02	1.6	0.015	0.4	2	
16/01/2025	7.9	43	NV	0.04	1.1	0.036	0.4	1.5	
10/05/2024	7.7	62	NV	<0.02	4.6	<0.005	1.1	5.7	217 mm of rainfall was received between 1 and 10 May 2024
09/05/2024	7.8	73	NV	<0.02	4.4	<0.005	0.7	5.1	
08/05/2024	7.7	70	NV	<0.02	3.7	<0.005	0.4	4.1	
07/05/2024	7.7	84	NV	<0.02	3.8	<0.005	0.5	4.3	
06/05/2024	7.6	70	NV	<0.02	3.3	0.60	<0.1	3.9	
05/05/2024	7.7	66	NV	<0.02	2.8	1.0	<0.1	3.8	



Building something great

Date	EPL ID 1 – A2 Dam								
	pH	TSS (mg/L)	O&G	Ammonia as N (mg/L)	Nitrate as N (mg/L)	Nitrite as N (mg/L)	TKN – N (mg/L)	Nitrogen (Total) (mg/L)	Comments
04/05/2024	7.7	84	NV	<0.02	3.5	0.30	<0.1	3.8	
03/05/2024	7.9	77	NV	<0.02	5.0	<0.005	0.4	5.3	
02/05/2024	7.8	47	NV	<0.02	5.3	0.005	0.2	5.5	



**Building something great**

**Table 2: EPL ID Point 2 – Discharge from Sediment Basin B4**

Date	EPL ID 2 – Sediment Basin 4								Comments	
	pH	TSS (mg/L)	O&G	Ammonia as N (mg/L)	Nitrate as N (mg/L)	Nitrite as N (mg/L)	TKN – N (mg/L)	Nitrogen (Total) (mg/L)		
15/08/2025	8.1	38	NV	<0.02	0.58	0.02	0.2	0.8	The site received 198.2 mm of rainfall between 30 July and 11 August 2025	
13/08/2025	8	39	NV	0.05	0.56	0.02	<0.1	0.6		
12/08/2025	7.9	49	NV	0.03	0.59	0.02	<0.1	0.6		
11/08/2025	7.8	52	NV	0.02	0.4	0.02	0.5	0.9		
8/08/2025	8	67	NV	0.02	0.51	0.02	0.2	0.7		
7/08/2025	8	77	NV	0.03	0.53	0.02	0.2	0.7		
6/08/2025	8	76	NV	0.03	0.55	0.02	0.2	0.7		
5/08/2025	8.1	110	NV	0.02	0.77	0.03	<0.1	0.8		
4/08/2025	8.1	120	NV	0.03	0.76	0.03	0.3	1		
3/08/2025	8	120	NV	0.02	0.75	0.03	0.2	1		
4/07/2025	8.1	160	NV	<0.02	0.54	0.009	<0.1	0.6		The site received 91.6 mm of rainfall between 30 June and 3 July 2025
3/07/2025	8.1	200	NV	0.02	0.5	0.009	0.2	0.7		
2/07/2025	8.1	210	NV	<0.02	0.49	0.009	0.1	0.6		
30/05/2025	8.7	210	NV	<0.02	0.65	0.02	<0.1	0.7	The site received 497 mm of rainfall between the period 8 May and 23 May 2025	
29/05/2025	8.2	140	NV	0.03	0.71	0.02	0.1	0.8		
28/05/2025	7.8	60	NV	<0.02	4.5	0.006	0.1	4.6		
27/05/2025	9.4	110	NV	<0.02	0.096	0.056	0.8	1		
26/05/2025	8.6	110	NV	0.02	0.93	0.061	<0.1	1		
24/05/2025	8	72	NV	0.02	1.1	0.063	<0.1	1.1		
23/05/2025	7.9	46	NV	0.02	0.98	0.05	<0.1	1		
21/05/2025	8	45	NV	0.02	1	0.05	<0.1	1.1		
20/05/2025	No sample was able to be collected due to flood waters									
19/05/2025	No sample was able to be collected due to flood waters									
17/05/2025	7.9	33	NV	0.02	0.96	0.04	<0.1	1		
16/05/2025	8	23	NV	0.03	0.94	0.03	<0.1	1		
5/05/2025	7.9	34	345	<0.02	0.89	0.02	<0.1	1	Greater than 170 mm of rainfall	



**Building something great**

Date	EPL ID 2 – Sediment Basin 4								Comments
	pH	TSS (mg/L)	O&G	Ammonia as N (mg/L)	Nitrate as N (mg/L)	Nitrite as N (mg/L)	TKN – N (mg/L)	Nitrogen (Total) (mg/L)	
3/05/2025	7.4	16	401	<0.02	3.6	<0.005	0.1	3.7	was recorded between 27 April and 2 May 2025
2/05/2025	7.9	67	318	<0.02	0.7	0.02	0.5	1.2	
1/05/2025	7.9	72	315	<0.02	0.69	0.01	<0.1	0.7	
30/04/2025	7.9	92	306	<0.02	0.67	0.01	0.2	0.9	
29/04/2025	8	140	314	<0.02	0.72	0.01	0.3	1.1	
28/04/2025	8	220	311	0.02	0.57	0.01	0.5	1	
29/01/2025	7.5	<5	NV	0.02	0.07	0.007	0.4	0.5	Greater than 365 mm of rainfall was recorded between 16 and 29 January 2025
28/01/2025	7.5	6	NV	0.09	0.14	0.012	1.4	1.5	
27/01/2025	7.5	14	NV	0.12	0.14	0.031	1.6	1.7	
26/01/2025	7.5	7	NV	0.04	0.13	0.014	0.5	0.6	
25/01/2025	7.4	10	NV	0.09	0.14	0.016	1.3	1.5	
24/01/2025	7.8	18	NV	<0.02	1.2	0.015	0.1	1.4	
23/01/2025	7.7	25	NV	<0.02	0.85	0.019	0.2	1	
22/01/2025	7.5	40	NV	<0.02	0.97	<0.005	0.3	1.3	
21/01/2025	7.4	70	NV	<0.02	0.97	0.017	0.3	1.3	
20/01/2025	7.7	120	NV	<0.02	1.1	0.015	0.3	1.4	
19/01/2025	7.7	120	NV	<0.02	1	0.016	0.1	1.2	
18/01/2025	7.7	130	NV	0.02	1	0.016	0.2	1.3	
17/01/2025	7.7	130	NV	<0.02	0.45	0.022	0.2	0.7	
16/01/2025	7.5	26	NV	0.02	0.2	0.019	0.3	0.5	
10/01/2025	7.9	180	NV	<0.02	0.62	0.013	<0.1	0.7	
09/01/2025	7.7	220	NV	0.02	0.41	0.032	0.3	0.7	
18/07/2024	7.9	7	NV	0.02	0.32	<0.005	0.1	0.4	217 mm of rainfall was received between 1 and 10 May 2024
10/05/2024	7.8	84	NV	<0.02	0.82	0.012	0.1	0.9	
09/05/2024	7.4	20	NV	<0.02	0.061	<0.005	0.5	0.6	
08/05/2024	7.4	31	NV	0.02	0.12	<0.005	0.5	0.6	
07/05/2024	7.5	58	NV	<0.02	0.23	<0.005	0.4	0.6	
06/05/2024	7.3	21	NV	<0.02	0.067	0.60	<0.1	0.6	
05/05/2024	7.0	84	NV	<0.02	2.0	<0.005	<0.1	2.0	



**Building  
something  
great**

Date	EPL ID 2 – Sediment Basin 4								
	pH	TSS (mg/L)	O&G	Ammonia as N (mg/L)	Nitrate as N (mg/L)	Nitrite as N (mg/L)	TKN – N (mg/L)	Nitrogen (Total) (mg/L)	Comments
04/05/2024	7.8	44	NV	<0.02	1.8	0.40	<0.1	2.2	
03/05/2024	7.9	140	NV	<0.02	0.56	0.009	0.1	0.7	
02/05/2024	7.9	76	NV	<0.02	0.38	0.009	0.1	0.5	

Table 3: EPL ID Point 3 – Discharge from Sediment Basin C2

Date	EPL ID 3 – Sediment Basin C2								Comments	
	pH	TSS (mg/L)	O&G	Ammonia as N (mg/L)	Nitrate as N (mg/L)	Nitrite as N (mg/L)	TKN – N (mg/L)	Nitrogen (Total) (mg/L)		
6/08/2025	7.7	52	NV	0.03	1.5	0.02	0.1	1.7	The site received 198.2 mm of rainfall between 30 July and 11 August 2025	
5/08/2025	7.7	64	NV	0.02	2.3	0.02	0.1	2.4		
4/08/2025	7.7	67	NV	0.02	2.3	0.02	<0.1	2.4		
3/08/2025	7.7	68	NV	0.02	2.3	0.02	<0.1	2.4		
4/07/2025	8	40	NV	<0.02	0.52	<0.005	<0.1	0.5	The site received 91.6 mm of rainfall between 30 June and 3 July 2025	
3/07/2025	8	62	NV	0.02	0.51	<0.005	<0.1	0.6		
2/07/2025	7.9	66	NV	0.02	0.51	<0.005	<0.1	0.6		
30/05/2025	7.8	28	NV	<0.02	2.5	0.007	0.2	2.7	The site received 497 mm of rainfall between the period 8 May and 23 May 2025	
29/05/2025	7.8	34	NV	0.02	2.6	0.007	<0.1	2.7		
28/05/2025	7.9	41	NV	0.02	3.1	0.01	0.2	3.3		
27/05/2025	7.8	38	NV	0.02	3	0.01	<0.1	3.1		
26/05/2025	7.9	12	NV	0.02	3.7	0.01	0.2	4		
24/05/2025	7.9	26	NV	0.02	3.5	0.008	0.3	3.8		
23/05/2025	7.9	64	NV	<0.02	2	<0.005	0.1	2.1		
21/05/2025	8.2	110	NV	<0.02	1.2	0.093	<0.1	1.4		
20/05/2025	No sample was able to be collected due to flood waters									
19/05/2025	No sample was able to be collected due to flood waters									
17/05/2025	7.7	98	NV	0.02	3.3	0.01	0.1	3.4		Greater than 170 mm of rainfall was recorded between 27 April and 2 May 2025
16/05/2025	7.7	100	NV	<0.02	4.6	0.01	0.3	4.9		
2/05/2025	7.7	160	NV	<0.02	2.8	0.006	0.2	3		
1/05/2025	7.9	180	NV	<0.02	4.6	0.01	0.2	4.7		
30/04/2025	7.9	190	NV	0.03	4.9	0.009	0.2	5		
29/04/2025	7.8	240	NV	0.02	5.2	0.007	2.7	7.9		
28/04/2025	7.9	600	NV	<0.02	4.7	<0.005	2.2	6.9		



**Building something great**

Date	EPL ID 3 – Sediment Basin C2								Comments
	pH	TSS (mg/L)	O&G	Ammonia as N (mg/L)	Nitrate as N (mg/L)	Nitrite as N (mg/L)	TKN – N (mg/L)	Nitrogen (Total) (mg/L)	
29/01/2025	8.1	<5	NV	<0.02	0.77	0.013	0.3	1.1	Greater than 365 mm of rainfall was recorded between 16 and 29 January 2025
28/01/2025	8.1	5	NV	0.04	1	0.013	0.3	1.4	
27/01/2025	8	5	NV	0.07	1.1	0.021	0.4	1.5	
26/01/2025	8	<5	NV	0.06	0.96	0.014	0.5	1.5	
25/01/2025	8	7	NV	0.05	0.3	0.007	0.5	0.8	
24/01/2025	7.9	17	NV	<0.02	1.2	0.015	0.1	1.4	
23/01/2025	7.9	18	NV	<0.02	1.5	0.014	0.2	1.7	
22/01/2025	7.8	19	NV	<0.02	1.9	<0.005	0.2	2.1	
21/01/2025	7.7	24	NV	<0.02	2	0.014	0.4	2.4	
20/01/2025	7.8	25	NV	0.02	2.6	0.016	0.8	3.4	
19/01/2025	7.8	<b>33</b>	NV	<0.02	2.6	0.017	0.7	3.3	
18/01/2025	7.8	<b>32</b>	NV	0.02	2.6	0.016	0.7	3.3	
17/01/2025	7.7	<b>300</b>	NV	0.02	1.1	0.011	0.2	1.3	
16/01/2025	6.8	<b>590</b>	NV	<0.02	0.37	<0.005	0.4	0.8	
10/01/2025	7.7	<b>150</b>	NV	0.03	2.0	0.012	<0.1	2.0	156 mm of rainfall was received between 7 and 9 Jan 2024
09/01/2025	7.7	<b>340</b>	NV	0.02	1.4	0.012	<0.1	1.4	
18/07/2024	8.0	20	NV	<0.02	2.4	0.006	<0.1	2.1	217 mm of rainfall was received between 1 and 10 May 2024
10/05/2024	7.7	<b>54</b>	NV	<0.02	3.9	0.005	0.4	4.4	
09/05/2024	7.7	12	NV	<0.02	4.1	<0.005	1.1	5.3	
08/05/2024	7.5	25	NV	<0.02	3.4	0.005	<0.1	3.5	
07/05/2024	7.6	22	NV	<0.02	3.8	0.005	0.3	4.1	
06/05/2024	7.6	<b>41</b>	NV	<0.02	2.1	<0.005	<0.1	2.1	
05/05/2024	7.5	28	NV	<0.02	1.5	0.30	<0.1	1.8	
03/05/2024	7.7	<b>70</b>	NV	<0.02	2.3	0.01	<0.1	2.1	
02/05/2024	7.7	<b>94</b>	NV	<0.02	1.8	0.008	<0.1	1.5	



**Building something great**

Table 4: EPL ID Point 4 – Discharge from Sediment Basin E1

Date	EPL ID 4 – Sediment Basin E1								Comments
	pH	TSS (mg/L)	O&G	Ammonia as N (mg/L)	Nitrate as N (mg/L)	Nitrite as N (mg/L)	TKN – N (mg/L)	Nitrogen (Total) (mg/L)	
5/08/2025	8	27	NV	0.02	0.81	<0.005	<0.1	0.8	The site received 198.2 mm of rainfall between 30 July and 11 August 2025
4/08/2025	8	30	NV	0.02	0.83	<0.005	<0.1	0.8	
3/08/2025	8	32	NV	0.02	0.8	<0.005	<0.1	0.8	
4/07/2025	7.8	94	NV	0.02	2.3	0.01	"0.1	2.3	
3/07/2025	7.7	190	NV	0.03	2	0.01	"0.1	2.1	The site received 91.6 mm of rainfall between 30 June and 3 July 2025
2/07/2025	7.7	190	NV	0.03	2	0.01	0.1	2.2	
24/05/2025	8	9	NV	0.02	1.1	0.005	<0.1	1.1	
23/05/2025	7.9	120	NV	<0.02	0.23	<0.005	0.1	0.3	The site received 497 mm of rainfall between the period 8 May and 23 May 2025
21/05/2025	7.9	44	NV	<0.02	0.69	<0.005	<0.1	0.7	
20/05/2025	No sample was able to be collected due to flood waters								
19/05/2025	No sample was able to be collected due to flood waters								
17/05/2025	7.9	24	NV	0.02	0.8	<0.005	0.1	0.9	Greater than 170 mm of rainfall was recorded between 27 April and 2 May 2025
16/05/2025	8	480	NV	0.02	0.27	<0.005	0.2	0.5	
5/05/2025	8.1	11	NV	<0.02	0.85	<0.005	<0.1	0.9	
3/05/2025	7.9	33	NV	<0.02	4.3	0.01	0.1	4.4	
2/05/2025	8	58	NV	<0.02	0.53	<0.005	<0.1	0.7	
1/05/2025	8	31	NV	<0.02	1	0.007	<0.1	1.1	
30/04/2025	8	28	NV	0.02	1.1	0.007	0.1	1.3	
29/04/2025	8	27	NV	<0.02	1.2	0.005	0.4	1.6	
28/04/2025	8	220	NV	<0.02	0.47	0.006	0.3	0.8	
29/01/2025	8.3	13	NV	<0.02	0.24	0.007	0.4	0.7	
28/01/2025	8.3	8	NV	0.05	0.3	0.007	0.5	0.8	
27/01/2025	8.3	10	NV	0.05	0.3	0.007	0.6	0.9	
26/01/2025	8.3	5	NV	0.05	0.3	0.009	0.5	0.8	



**Building something great**

Date	EPL ID 4 – Sediment Basin E1								Comments
	pH	TSS (mg/L)	O&G	Ammonia as N (mg/L)	Nitrate as N (mg/L)	Nitrite as N (mg/L)	TKN – N (mg/L)	Nitrogen (Total) (mg/L)	
25/01/2025	8.3	10	NV	0.05	0.3	0.007	0.5	0.8	
20/01/2025	7.7	73	NV	0.04	0.17	0.01	0.3	0.5	
19/01/2025	7.8	73	NV	0.04	0.17	0.01	0.3	0.5	
18/01/2025	7.7	73	NV	0.04	0.17	0.01	0.3	0.5	
17/01/2025	8	340	NV	0.02	0.46	0.017	0.4	0.8	
16/01/2025	7.9	560	NV	0.02	0.87	0.018	0.3	1.2	
10/01/2025	8.1	48	NV	<0.02	1.8	0.008	<0.1	1.9	
09/01/2025	7.8	72	NV	<0.02	0.95	0.006	0.1	1.1	
18/07/2024	8.0	10	NV	<0.02	0.42	<0.005	<0.1	0.5	
10/05/2024	7.9	21	NV	<0.02	1.7	0.014	0.3	2.0	217 mm of rainfall was received between 1 and 10 May 2024
09/05/2024	8.0	16	NV	<0.02	2.3	0.014	0.6	2.9	
08/05/2024	7.9	73	NV	<0.20	0.20	<0.005	0.2	0.4	
07/05/2024	7.9	98	NV	<0.02	0.21	0.005	0.2	0.4	
06/05/2024	8.1	66	NV	<0.02	0.81	0.30	<0.1	1.1	
05/05/2024	7.9	72	NV	<0.02	0.24	0.30	<0.1	0.5	
03/05/2024	7.9	42	NV	<0.02	0.98	<0.005	<0.1	1.0	
02/05/2024	7.7	58	NV	<0.02	0.44	<0.005	0.1	0.6	



**Building something great**

**Table 5: EPL ID Point 5 – Discharge from Sediment Basin E2**

Date	EPL ID 5 – Sediment Basin E2								Comments
	pH	TSS (mg/L)	O&G	Ammonia as N (mg/L)	Nitrate as N (mg/L)	Nitrite as N (mg/L)	TKN – N (mg/L)	Nitrogen (Total) (mg/L)	
5/08/2025	7.9	80		0.02	0.65	<0.005	<0.1	0.7	The site received 198.2 mm of rainfall between 30 July and 11 August 2025
4/08/2025	7.9	78		0.03	0.62	<0.005	<0.1	0.6	
3/08/2025	7.9	89		0.03	0.63	<0.005	<0.1	0.7	
4/07/2025	7.9	97	NV	<0.02	0.75	0.01	0.1	0.9	The site received 91.6 mm of rainfall between 30 June and 3 July 2025
3/07/2025	7.9	96	NV	0.02	0.81	0.01	0.2	1	
2/07/2025	7.9	90	NV	0.02	0.81	0.01	0.1	1	
23/05/2025	7.9	42	NV	<0.02	0.82	<0.005	<0.1	0.9	The site received 497 mm of rainfall between the period 8 May and 23 May 2025
21/05/2025	8	17	NV	<0.02	1.3	<0.005	<0.1	1.3	
20/05/2025	No sample was able to be collected due to flood waters								
19/05/2025	No sample was able to be collected due to flood waters								Greater than 170 mm of rainfall was recorded between 27 April and 2 May 2025
16/05/2025	7.9	96	NV	<0.02	0.56	<0.005	<0.1	0.6	
1/05/2025	7.9	120	NV	0.02	0.12	0.01	0.3	0.4	
30/04/2025	7.9	110	NV	0.02	0.23	0.009	0.2	0.4	Greater than 365 mm of rainfall was recorded between 16 and 29 January 2025
29/04/2025	7.8	85	NV	<0.02	0.25	0.005	0.4	0.7	
28/04/2025	8	98	NV	0.02	0.87	<0.005	0.3	1.2	
24/01/2025	8.2	13	NV	<0.02	0.97	0.015	0.1	1.4	Greater than 365 mm of rainfall was recorded between 16 and 29 January 2025
23/01/2025	8.1	9	NV	<0.02	1.2	0.014	0.2	1.4	
22/01/2025	8.1	16	NV	<0.02	1.4	<0.005	0.2	1.6	
21/01/2025	8	11	NV	<0.02	1.5	0.014	0.4	1.9	
20/01/2025	8	10	NV	0.02	1.7	0.01	<0.1	1.8	
19/01/2025	8	13	NV	<0.02	1.7	0.01	0.1	1.9	
18/01/2025	8	12	NV	0.02	1.7	0.01	0.1	1.8	
17/01/2025	8	110	NV	<0.02	0.83	0.005	<0.1	0.9	
16/01/2025	7.9	470	NV	<0.02	0.5	0.012	<0.1	0.6	



**Building  
something  
great**

Date	EPL ID 5 – Sediment Basin E2								
	pH	TSS (mg/L)	O&G	Ammonia as N (mg/L)	Nitrate as N (mg/L)	Nitrite as N (mg/L)	TKN – N (mg/L)	Nitrogen (Total) (mg/L)	Comments
09/01/2024	7.9	<b>130</b>	NV	0.02	1.1	0.007	0.2	1.2	156 mm of rainfall was received between 7 and 9 Jan 2024
18/07/2024	8.0	19	NV	0.02	0.02	<0.005	0.3	0.3	
10/05/2024	7.8	<b>68</b>	NV	0.04	0.13	0.006	0.5	0.6	217 mm of rainfall was received between 1 and 10 May 2024
09/05/2024	7.9	<b>110</b>	NV	<0.02	0.14	0.007	0.2	0.4	
08/05/2024	7.9	<b>33</b>	NV	<0.02	1.8	0.007	0.2	2.0	
07/05/2024	8.0	<b>32</b>	NO	<0.02	1.8	0.01	0.2	2.0	
06/05/2024	8.0	<b>52</b>	NV	<0.02	0.93	0.40	<0.1	1.4	
05/05/2024	7.9	28	NV	<0.02	1.4	0.70	<0.1	2.0	
03/05/2024	7.9	<b>160</b>	NV	0.02	0.52	0.02	0.1	0.7	
02/05/2024	8.0	<b>160</b>	NV	<0.02	0.74	0.02	<0.1	0.7	



**Building something great**

Table 6: Surface Water Monitoring Results Prior to 19 April 2024

Date	EPL ID 1			EPL ID 2			EPL ID 3			EPL ID 4			EPL ID 5			Comments
	pH	TSS (mg/L)	O&G	pH	TSS (mg/L)	O&G	pH	TSS (mg/L)	O&G	pH	TSS (mg/L)	O&G	pH	TSS (mg/L)	O&G	
10/04/2024	7.7	44	NV	7.6	27	NV	7.7	29	NV	8.1	39	NV	7.9	22	NV	
09/04/2024	7.8	60	NV	7.7	28	NV	7.6	53	NV	8.0	31	NV	7.7	35	NV	
07/04/2024	7.8	72	NV	7.9	84	NV	7.7	23	NV	7.9	22	NV	7.7	42	NV	
06/04/2024	7.8	45	NV	8.1	350	NV	7.7	67	NV	7.8	19	NV	8.0	120	NV	
22/02/2024				7.7	50	NV	7.6	35	NV	7.7	19	NV	7.7	25	NV	
21/02/2024	7.8	46	NV	7.8	66	NV	7.7	58	NV	7.8	34	NV	7.8	32	NV	
20/02/2024	7.9	56	NV	7.9	76	NV	7.7	87	NV	8.0	140	NV	7.9	97	NV	
22/12/2023	7.7	47	NV				7.7	90	NV	7.8	150	NV	7.7	98	NV	
21/12/2023	7.7	71	NV				7.6	230	NV	7.9	220	NV	7.9	240	NV	
20/12/2023							7.6	310	NV	8.0	1,120	NV	8.1	790	NV	
07/12/2023							7.7	5	NV							
17/11/2023				7.5	22	NV	7.7	16	NV	8.0	22	NV	8.0	21	NV	
09/11/2023				7.6	7	NV	7.6	25	NV	8.0	46	NV	7.9	44	NV	
12/10/2023							8.0	6	NV							
21/4/2023	7.8	78	NV													
25/10/2022	7.5	40	NV													
24/10/2022	7.6	8	NV													
21/10/2022	7.2	13	NV													



**Building  
something  
great**

Date	EPL ID 1			EPL ID 2			EPL ID 3			EPL ID 4			EPL ID 5			Comments
20/10/2022	7.7	14	NV													
12/10/2022	7.6	11	NV													
10/10/2022	7.6	35	NV													
15/7/2022	NPH	22	NV													312mm of rainfall 2/7/23 to 15/07/23
14/7/2022	NPH	38	NV													312mm of rainfall 2/7/23 to 15/07/23
13/7/2022	NPH	49	NV													312mm of rainfall 2/7/23 to 15/07/24
11/7/2022	NPH	60	NV													312mm of rainfall 2/7/23 to 15/07/25
9/7/2022	NPH	92	NV													312mm of rainfall 2/7/23 to 15/07/26
8/7/2022	NPH	120	NV													312mm of rainfall 2/7/23 to 15/07/26
7/7/2022	NPH	124	NV													312mm of rainfall 2/7/23 to 15/07/26
6/7/2022	NPH	104	NV													312mm of rainfall 2/7/23 to 15/07/26
12/4/2022	NPH	13	NV													
11/4/2022	NPH	12	NV													
8/4/2022	NPH	29	NV													
31/3/2022	7.9	66	NV													
30/3/2022	7.8	56	NV													



**Building  
something  
great**

Date	EPL ID 1			EPL ID 2			EPL ID 3			EPL ID 4			EPL ID 5			Comments
25/3/2022	7.8	27	NV													
11/3/2022	7.5	37	NV													
10/3/2022	7.0	41	NV													
9/3/2022	7.5	7.6	NV													
8/3/2022	7.8	47	NV													
7/3/2022	6.9	43	NV													
4/3/2022	7.5	51	NV													
3/3/2022	NPH	135	NV													
2/3/2022	6.7	32	NV													
21/1/2022	6.9	9	NV													
20/1/2022	6.8	13	NV													
2/11/2021	NPH	14	NV													
30/3/2021	7.5	17	NV													
29/03/2021	7.6	22	NV													
26/03/2021	7.5	26	NV													
25/03/2021	7.5	18	NV													
24/03/2021	7.8	92	NV													
23/03/2021	7.9	85	NV													
22/03/2021	7.4	61	NV													
21/03/2021	7.3	46	NV													
20/03/2021	7.3	32	NV													



**Building  
something  
great**

Date	EPL ID 1			EPL ID 2			EPL ID 3			EPL ID 4			EPL ID 5			Comments
19/03/2021	7.3	39	NV													
18/03/2021	7	25	NV													
17/03/2021	7.0	32	NV													
16/03/2021	6.8	20	NV													
15/03/2021	7.4	6	NV													
29/07/2020	7	8	NV													
28/07/2020	7.3	9.5	NV													
27/07/2020	8.3	10	NV													
17/07/2020	7.5	11	NV													
16/07/2020	7.5	18	NV													
15/07/2020	8.3	10	NV													
28/02/2020	7.1	20	NV													
27/02/2020	7.0	18	NV													
26/02/2020	7.2	17	NV													
25/02/2020	7.1	16	NV													
24/02/2020	7.1	17	NV													
21/02/2020	7.9	11	NV													
20/02/2020	7.9	10	NV													
19/02/2020	7.9	12	NV													
18/02/2020	8	5	NV													
17/02/2020	7.9	14	NV													



**Building something great**

Date	EPL ID 1			EPL ID 2			EPL ID 3			EPL ID 4			EPL ID 5			Comments
14/02/2020	8.0	10	NV													
13/02/2020	8.0	12	NV													
12/02/2020	8.1	22	NV													
11/02/2020	7.7	17	NV													

Notes:

NV = Not Visible

**TABLE 7: Surface Water Monitoring Results – Corrections Log**

Date of Data (sample Date)	Old Published Data	Corrected Data	Reason for Update / Correction	Update Person	Date corrected Data Published	Comments

Note: The table above details the corrections made to published data due to incorrect reporting or misleading published data



Building something great

FIGURE 1 Seaham Quarry- Surface Water Monitoring Locations

Seaham Quarry – Water Discharge Monitoring Locations



Water Discharge 1 (A2 Dam)	EPA ID 1	-32.681245	151.789430
Water Discharge 2 (Basin B4)	EPA ID 2	-32.676472	151.794833
Water Discharge 3 (Basin C2)	EPA ID 3	-32.680100	151.798745
Water Discharge 4 (Basin E1)	EPA ID 4	-32.680455	151.791851
Water Discharge 5 (Basin E2)	EPA ID 5	-32.679933	151.792793