



# Hall Quarry

## Environmental Monitoring Report

October 2020

Date Published: Oct 2020



This monitoring report is to satisfy the requirements of Section 66 (6) of the Protection of the Environment and Operations Act 1997, to make available, within 14 days of obtaining any monitoring data that relates to pollution under an Environment Protection Licence.

The monitoring of pollutants provided in this report is undertaken as per the requirements of Environment Protection Licence 4082 (EPL 4082 – Boral Hall Quarry)

This report provides environmental monitoring data for Hall Quarry for the period November 2017 to October 2020.

Hall Quarry Information	
Premise Details	Boral – Hall Quarry
Address	Kaveney Rd, Murrumbateman NSW 2582
Licensee	Boral Resources (Country) Pty Ltd
EPL No	4082
EPL Location	<a href="http://www.epa.nsw.gov.au/prpoeoapp/ViewPOEOLicence.aspx?DOCID=33148&amp;SYSUID=1&amp;LICID=4082">http://www.epa.nsw.gov.au/prpoeoapp/ViewPOEOLicence.aspx?DOCID=33148&amp;SYSUID=1&amp;LICID=4082</a>

Monitoring data in this report relates to the monitoring undertaken for the following environmental pollutants:

- Blasting

## Blasting

Blast monitoring is conducted as per condition L6.3 of EPL 4082. The blasting monitoring results are summarised below.

Monitoring Period: October 2020  
 Licensee: Hall Quarry  
 Licensee Address: Kaveney's Rd, Murrumbateman NSW 2582  
 EPL No: 4082

### Qualifications related to blasting:

The airblast overpressure level from blasting operations in or on the premises must not exceed:

- a) 115 dB (Lin Peak) for more than 5% of the total number of blasts during each reporting period; and
- b) 120 dB (Lin Peak) at any time.

The ground vibration peak particle velocity from blasting operations carried out in or on the premises must not exceed:

- a) 5mm/s for more than 5% of the total number of blasts carried out on the premises during each reporting period; and
- b) 10 mm/s at any time.

Airblast overpressure and ground vibration levels must be measured at most affected residence or noise sensitive location that is not owned by the licensee or subject to a private agreement between the owner of the residence or noise sensitive location and the licensee as to an alternative overpressure level.

Results							
Location	Blast Date	Results Received	Blast Time	Ground Vibration Result	GV Compliant	Overpressure Result	OP Compliant
Quarry Hill	19/10/20	19/10/20	12:52	1.397 mm/s	Yes	102.8 dBL	Yes
Silverwattle	19/10/20	19/10/20	12:52	0.51 mm/s	Yes	100 dBL	Yes
Quarry Hill	29/07/20	29/07/20	12:16	1.78 mm/s	Yes	102.8 dBL	Yes
Silverwattle	29/07/20	29/07/20	12:16	0.51 mm/s	Yes	100 dBL	Yes
Quarry Hill	10/06/20	10/06/20	14:03	1.651 mm/s	Yes	102.8 dBL	Yes
Silverwattle	10/06/20	10/06/20	14:03	0.51 mm/s	Yes	100 dBL	Yes
Quarry Hill	19/05/20	19/05/20	13:13	1.524 mm/s	Yes	107 dBL	Yes
Silverwattle	19/05/20	19/05/20	13:13	0.51 mm/s	Yes	100 dBL	Yes
Quarry Hill	01/04/20	01/04/20	14:40	1.470 mm/s	Yes	103.5 dBL	Yes
Silverwattle	01/04/20	01/04/20	14:40	0.51 mm/s	Yes	100 dBL	Yes
Quarry Hill	11/03/20	11/03/20	12:56	0.823 mm/s	Yes	108.4 dBL	Yes
Silverwattle	11/03/20	11/03/20	12:56	0.51 mm/s	Yes	100 dBL	Yes
Quarry Hill	17/02/20	17/02/20	13:00	1.37 mm/s	Yes	107 dBL	Yes
Silverwattle	17/02/20	17/02/20	13:00	0.684 mm/s	Yes	100 dBL	Yes
Quarry Hill	26/11/19	26/11/19	15:02	0.51 mm/s	Yes	124.4 dBL	Yes
Silverwattle	26/11/19	26/11/19	15:02	No trigger	Yes	No trigger	Yes
Quarry Hill	27/9/19	27/9/19	13:08	1.055 mm/s	Yes	111.5 dBL	Yes
Silverwattle	27/9/19	27/9/19	13:08	0.51mm/s	Yes	100 dBL	Yes
Quarry Hill	17/6/19	17/6/19	14:23	0.51mm/s	Yes	102.8 dBL	Yes
Silverwattle	17/6/19	17/6/19	14:23	0.51mm/s	Yes	103.5 dBL	Yes
Quarry Hill	6/5/19	6/5/19	13:49	0.51mm/s	Yes	94 dBL	Yes
Silverwattle	6/5/19	6/5/19	13:49	0.51mm/s	Yes	100 dBL	Yes

Quarry Hill	29/4/19	29/4/19	12:21	0.51mm/s	Yes	103.5 dBL	Yes
Silverwattle	29/4/19	29/4/19	12:21	0.51mm/s	Yes	100 dBL	Yes
Quarry Hill	29/1/19	29/1/19	13:05	0.51mm/s	Yes	100 dBL	Yes
Silverwattle	29/1/19	29/1/19	13:05	0.51mm/s	Yes	100 dBL	Yes
Quarry Hill	18/1/19	18/1/19	12:44	0.51mm/s	Yes	101.9 dBL	Yes
Silverwattle	18/1/19	18/1/19	12:44	0.51mm/s	Yes	100 dBL	Yes
Quarry Hill	5/12/18	5/12/18	13:13	0.51mm/s	Yes	100 dBL	Yes
Silverwattle	5/12/18	5/12/18	13:13	0.51mm/s	Yes	100 dBL	Yes
Quarry Hill	27/11/2018	27/11/2018	13:13	0.51mm/s	Yes	100 dBL	Yes
Silverwattle	27/11/2018	27/11/2018	13:13	0.51mm/s	Yes	100 dBL	Yes
Quarry Hill	30/10/2018	30/10/2018	13:21	0.51mm/s	Yes	106 dBL	Yes
Silverwattle	30/10/2018	30/10/2018	13:21	0.51mm/s	Yes	105.5 dBL	Yes
Quarry Hill	22/10/2018	22/10/2018	11:45	0.51mm/s	Yes	100 dBL	Yes
Silverwattle	22/10/2018	22/10/2018	11:45	0.51mm/s	Yes	100 dBL	Yes
Quarry Hill	24/9/2018	25/9/2018	13:33	0.51mm/s	Yes	104.2	Yes
Silverwattle	24/9/2018	25/9/2018	13:33	0.51mm/s	Yes	100 dBL	Yes
Quarry Hill	27/7/2018	27/7/2018	13:21	0.51 mm/s	Yes	103.5 dBL	Yes
Silverwattle	27/7/2018	27/7/2018	13:21	0.51 mm/s	Yes	100 dBL	Yes
Quarry Hill	5/6/2018	5/6/2018	13:29	0.51 mm/s	Yes	106.5 dBL	Yes
Silverwattle	5/6/2018	5/6/2018	13:29	0.38 mm/s	Yes	106.5 dBL	Yes
Quarry Hill	25/5/2018	25/5/2018	13:11	0.51 mm/s	Yes	105.5 dBL	Yes
Silverwattle	25/5/2018	25/5/2018	13:11	0.51mm/s	Yes	100 dBL	Yes
Quarry Hill	20/4/18	27/4/18	13:00	0.51 mm/s	Yes	105.5 dBL	Yes
Silver Wattle	20/4/18	27/4/18	13:00	0.51 mm/s	Yes	108 dBL	Yes
Quarry Hill	5/2/18	12/2/18	11:13	0.51 mm/s	Yes	100 dBL	Yes
Silver Wattle	5/2/18	12/2/18	11:13	0.51 mm/s	Yes	100 dBL	Yes
Quarry Hill	5/12/17	12/12/18	13:22	0.51 mm/s	Yes	109.5 dBL	Yes
Silver Wattle	5/12/17	12/12/2017	13:22	0.51 mm/s	Yes	100 dBL	Yes

## Hall Quarry Monitoring Locations.

### Blast Monitoring Location

